





Begin by wrapping the glass into a disk shape on the end of your headpin or shank.




Make the disk smaller than the size of the opening of your mold.



Add glass in the general shape of a cone and make it longer than the depth of your mold.



Heat the glass and push into the mold gently while using a flat tool to gently push down any glass that might come up around the headpin or shank.




For the four sided shape, do the same as above.







If you haven't added enough glass to fill the mold, add glass to the end of your shape, reheat and push gently into the mold again.



Use the flat tool to push down any glass that might come up around the headpin or shank.



For the triangle shape, add a small amount of glass to the end of your headpin or shank, push this into the top of the mold to begin the shape.



Add the glass in a long skinny shape, again longer than the depth of the mold.



Push gently into the mold and as explained above use your flat tool to push down any glass that may move up to the headpin or shank.

With the molds that have sharp lines, you can always add glass to the corners and tips for a sharper shape.

Decorate and have fun!!!